



		Do not scale from this drawing. Use figured dimensions in all cases. Verify dimensions on site and report any discrepancies to the Architects immediately. This drawing to be read in conjunction with the Architects specification. © this drawing is copyright and may only be reproduced with the Architects permission.
	——new natural slate on sw batter	IS
	——repair existing cast iron/alumir rainwater goods	nium
	——paint existing masonry (typical	)
	<ul> <li>new sliding sash timber windows to conservation architects details</li> </ul>	
	— cast iron rainwater pipes to be repaired and re-painted	
	-review condition of chimney	18th/19th Century high significance
<b>、</b>	stack coping & repair if required (typical)	mid late 20th Century low significance
	—new natural slate on sw battens	Proposed new Works
	—repair all lead flashing generally	Image:
	—paint existing masonry (typical)	P01 June 2022 LG PLANNING ISSUE REV DTE DRN ISSUE reddy architecture + urbanism Reddy Architecture + Urbanism Dublin Office,
	—new sliding sash timber windows to conservation architects details	Joartry Mills, Dartry Road, Dublin 6.         T: +353 (0)1 4987000         W: www.reddyarchitecture.com         E: info@reddyarchitecture.com         JOB         Glebe House Residential Development         St. Agnes Road, Crumlin, Dublin.
		CLIENT

		1.			
CLIENT Seabren Developments Ltd and Circle VHA CLG					
DRAWING GLEBE HOUSE DRAWINGS PROPOSED ELEVATIONS					
DATE June 2022	SCALE	1:50 @ A1			
DRN. N. Britz	CHECKED	M. Freaney			
JOB NO.	DWG	NO.	REVISION		
P19171D	132		P01		